

- You are here: Home / Vehicle Owners / VIN
- Search Safety Problems
 - › Vehicles
 - › Car Seats
 - › Tires
 - › Equipment
 - › Recalls by VIN
 - › Recalls FAQ
- Report Safety Problems
 - › Vehicle (Online)
 - › Vehicle (via PDF)
 - › Non-Vehicle
- Drive Safer
 - › Technology
 - › Driving Tips
 - › Tires
 - › Passenger Van Safety
 - › Emergency Response Vehicles
 - › Theft Prevention

Recalls Results by VIN - Vehicle Identification Number Print

VIN: 2A8HR54P28R833872
Year: 2008 **Make:** CHRYSLER **Model:** TOWN & COUNTRY
Number of Open Recalls: 5

NHTSA Recall Number: [10V-235](#) **Recall Date:** October 25, 2010
Manufacturer Recall Number: K14


SUMMARY:
 THE RIGHT AND/OR LEFT POWER SLIDING DOOR WIRING HARNESSES MAY CHAFE ON THE SLIDING DOOR HINGE WHEN OPERATING THE SLIDING DOOR

SAFETY RISK:
 THIS COULD CAUSE THE SLIDING DOOR LATCH TO OVERHEAT AND CAUSE A FIRE INSIDE THE SLIDING DOOR.

REMEDY:
 THE POWER SLIDING DOOR WIRING HARNESS AND THE DRIVE MOTOR WIRING HARNESS MUST BE INSPECTED FOR DAMAGE AND REPAIRED/REPLACED AS NECESSARY. THE TWO HARNESSES MUST THEN BE TIE STRAPPED TOGETHER AND ROUTED UNDER THE SLIDING DOOR WEATHER STRIP AND A TAB/WEDGE INSTALLED ON EACH SLIDING DOOR LOWER HINGE BRACKET.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 For more information, visit [recalls.mopar.com](#) or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Aug 29, 2020

NHTSA Recall Number: [10V-611](#) **Recall Date:** November 7, 2010
Manufacturer Recall Number: K25

SUMMARY:
 THE HEATING, VENTILATION AND AIR CONDITIONING (HVAC) DRAIN TUBE AND GROMMET MAY LEAK WATER ONTO THE PASSENGER COMPARTMENT CARPETING AND/OR THE OCCUPANT RESTRAINT CONTROL (ORC) MODULE.

SAFETY RISK:
 THIS CAN LEAD TO THE ILLUMINATION OF THE AIRBAG WARNING LIGHT AND THE POTENTIAL FOR AN INADVERTENT AIRBAG DEPLOYMENT WITHOUT WARNING.

REMEDY:
 THE HVAC DRAIN TUBE AND GROMMET MUST BE REPLACED.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 For more information, visit [recalls.mopar.com](#) or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Aug 29, 2020

NHTSA Recall Number: [14V-373](#) **Recall Date:** June 26, 2014
Manufacturer Recall Number: R03


SUMMARY:
 THE WIRELESS IGNITION NODE (WIN) MODULE MAY HAVE UNINTENTIONAL MOVEMENT OF THE FREQUENCY OPERATED BUTTON IGNITION KEY (FOB) FROM THE ON TO THE ACCESSORY POSITION WHILE DRIVING.

SAFETY RISK:
 THIS COULD CAUSE UNINTENDED ENGINE SHUT OFF AND INCREASE THE RISK OF A CRASH.

REMEDY:
 THE WIN MODULE AND FOBIS MUST BE REPLACED.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 For more information, visit [recalls.mopar.com](#) or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Aug 29, 2020

NHTSA Recall Number: [16V-047](#) **Recall Date:** January 26, 2016
Manufacturer Recall Number: S07


SUMMARY:
 THE OCCUPANT RESTRAINT CONTROL (ORC) MODULE ON YOUR VEHICLE MAY MALFUNCTION DUE TO CORROSION OF THE POWER SUPPLY INTEGRATED CIRCUIT.

SAFETY RISK:
 THIS COULD RESULT IN AN ILLUMINATED AIRBAG WARNING LAMP WITH THE POSSIBILITY OF NO AIRBAG DEPLOYMENT IN A CRASH NECESSITATING AIRBAG DEPLOYMENT OR AN INADVERTENT AIRBAG DEPLOYMENT WITHOUT AN ILLUMINATED AIRBAG WARNING LAMP.

REMEDY:
 THE OCCUPANT RESTRAINT CONTROL (ORC) MODULE MUST BE REPLACED.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 For more information, visit [recalls.mopar.com](#) or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Aug 29, 2020

NHTSA Recall Number: [20V-396](#) **Recall Date:** July 7, 2020
Manufacturer Recall Number: W09


SUMMARY:
 A loose or detached DAB emblem may result in either the emblem or retainers, or both, not remaining attached to the DAB cover during DAB deployment.

SAFETY RISK:
 A loose or detached emblem or emblem retainer can become a potential projectile during a crash with DAB deployment, which may result in occupant injury.

REMEDY:
 Replace the driver airbag cover.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 For more information, visit [recalls.mopar.com](#) or call 1-800-853-1403. Please have your VIN ready when calling.



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Aug 29, 2020

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues & Recalls](#) section and follow the instructions there.

Recall information for this manufacturer is only available going back to January 01, 1990. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

Enter another VIN here:

I'm not a robot

[Submit](#)