

Search **MyCarMax** Your Nearest Store Oxnard [Schedule an appraisal](#)
[Sign in](#) | [Register](#) [Change](#) | [Contact Us](#) | [Map](#) | [Website Feedback](#)

◀ [Previous car](#) | [Next car](#) ▶ Back to [search results](#) **2 people saved this car** [Set up a test drive now](#) [Facebook](#) [Twitter](#) [Pinterest](#) [Email](#) [Print](#) [Save this car](#)



[View Full Screen](#) CLICK TO ZOOM 1 of 32



CQC CARMAX QUALITY CERTIFIED **2006 Honda Accord LX 4D Sedan**
 Cruise Control, Overhead Airbags, Side Airbags [more...](#)

- No-haggle price \$13,998***
- 5-Day Money-Back Guarantee*... ✓
- Clean Title Guarantee*... ✓
- [CarMax Quality Certified](#)... ✓
- [Estimate monthly payments](#)

Quick Glance

Miles	28K
Drive	2WD
Transmission	Automatic
Exterior	Silver
Interior	Gray
EPA Mileage	24/34 MPG
Stock #	11209030
Rating	4.7 ★★★★★

[66 reviews](#) | [Write a review](#)

(805) 288-8006
 (855) 201-9668

- ▶ [Hold This Car](#)
- ▶ [Schedule Test Drive](#)
- ▶ [Schedule Appraisal](#)
- ▶ [Schedule Appointment](#)
- ▶ [Get Financing Info](#)
- ▶ [Ask a Question](#)

Current Location
 Oxnard
 2001 Lockwood St.
 Oxnard, CA 93036
 ▶ [Hours and directions](#)

Vehicle available as of 10/27/2014 4:08 PM Eastern Time VIN 3HGCM56496G701151

safercar.gov

HOME

VEHICLE SHOPPERS

VEHICLE OWNERS

VEHICLE MANUFACTURERS

PARENTS CENTRAL

You are here: Home / Vehicle Owners VIN

Do You Have a Safety Problem or Complaint?

[File a Complaint Now](#)

Search for all Recalls, Complaints & Investigations

[Recalls Look-up by VIN \(Vehicle Identification Number\)](#)[Recalls FAQ](#)

Receive Updates for Latest Recalls

[Sign-up for Email Alerts](#)[Subscribe to RSS Feeds](#)[Resources](#)[Databases \(Flat Files\)](#)[Passenger Van Safety](#)[Emergency Response Vehicles](#)

Recalls Results Look-up by VIN

[Print](#)**VIN:** 3HGCM56496G701151**Year:** 2006 **Make:** Honda **Model:** Accord Sedan**Number of Open Recalls:** 2**NHTSA Recall Number:** [14V-351](#)**Recall Date:** August 29, 2014**Manufacturer Recall Number:** JJ5**SUMMARY:**

AMERICAN HONDA MOTOR CO., INC. (HONDA) IS CONDUCTING A LIMITED REGIONAL RECALL FOR CERTAIN MODEL YEAR 2001-2007 ACCORD (4-CYLINDER), 2001-2002 ACCORD (V6), 2001-2005 CIVIC, 2002-2006 CR-V, 2003-2011 ELEMENT, 2002-2004 ODYSSEY, 2002-2007 PILOT AND 2006 RIDGELINE VEHICLES ORIGINALLY SOLD, OR CURRENTLY REGISTERED IN ALABAMA, FLORIDA, GEORGIA, HAWAII, LOUISIANA, MISSISSIPPI, SOUTH CAROLINA, TEXAS, PUERTO RICO AND THE U.S. VIRGIN ISLANDS, AND EQUIPPED WITH TAKATA-BRAND AIR BAG INFLATORS. UPON DEPLOYMENT OF THE DRIVER SIDE FRONTAL AIR BAG, EXCESSIVE INTERNAL PRESSURE MAY CAUSE THE INFLATOR TO RUPTURE.

SAFETY RISK:

IN THE EVENT OF A CRASH NECESSITATING DEPLOYMENT OF THE DRIVER SIDE FRONTAL AIR BAG, THE INFLATOR COULD RUPTURE WITH METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANTS.

REMEDY:

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE VEHICLES AND REPLACE ANY DEFECTIVE AIR BAG INFLATORS, AS NECESSARY, FREE OF CHARGE. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009. HONDA'S NUMBER FOR THIS RECALL IS JJ5, JG7, JG8, JG9, JH0, JH1 AND JH2.

RECALL STATUS: Recall **INCOMPLETE****MANUFACTURER NOTES:**

THIS RECALL DATA LAST REFRESHED: Oct 31, 2014

NHTSA Recall Number: [11V-395](#)**Recall Date:** August 3, 2011

FRONTAL AIR BAG, THE INFLATOR COULD RUPTURE WITH METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANTS.

REMEDY:

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE VEHICLES AND REPLACE ANY DEFECTIVE AIR BAG INFLATORS, AS NECESSARY, FREE OF CHARGE. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009. HONDA'S NUMBER FOR THIS RECALL IS JJ5, JG7, JG8, JG9, JH0, JH1 AND JH2.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Oct 31, 2014

NHTSA Recall Number: [11V-395](#)

Recall Date: August 3, 2011

Manufacturer Recall Number: R89

SUMMARY:

HONDA IS RECALLING CERTAIN MODEL YEAR 2005-2010 ACCORD, 2007-2010 CR-V, AND 2005-2008 ELEMENT PASSENGER CARS MANUFACTURED FROM JULY 1, 2004, THROUGH SEPTEMBER 3, 2010. THE OUTER RACE OF THE SECONDARY SHAFT BEARING MAY BE BROKEN DURING CERTAIN DRIVING STYLES. A BROKEN OUTER RACE MAY CAUSE ABNORMAL NOISE, THE MALFUNCTION INDICATOR LIGHT TO TURN ON, AND ALLOW CONTACT BETWEEN THE TRANSMISSION IDLE GEAR AND AN ELECTRONIC SENSOR HOUSING WITHIN THE TRANSMISSION.

SAFETY RISK:

THIS COULD RESULT IN A SHORT CIRCUIT CAUSING THE ENGINE TO STALL. ADDITIONALLY, BROKEN PIECES OF THE OUTER RACE OR BALL BEARING FROM THE SECONDARY SHAFT MAY BECOME LODGED IN THE PARKING PAWL RESULTING IN THE VEHICLE ROLLING AFTER THE DRIVER HAS PLACED THE GEAR SELECTOR IN THE PARK POSITION. ENGINE STALL AND UNEXPECTED VEHICLE MOVEMENT INCREASES THE RISK OF A CRASH OR PERSONAL INJURY TO PERSONS WITHIN THE PATH OF A ROLLING VEHICLE.

REMEDY:

HONDA WILL NOTIFY OWNERS AND DEALERS WILL UPDATE THE AUTOMATIC TRANSMISSION CONTROL MODULE SOFTWARE FREE OF CHARGE. THE SAFETY RECALL BEGAN ON AUGUST 27, 2011. OWNERS MAY CONTACT HONDA AUTOMOBILE CUSTOMER SERVICE AT 1-800-999-1009.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

THIS RECALL DATA LAST REFRESHED: Oct 31, 2014