



Your AutoCheck Vehicle History Report

Report Run Date: November 23, 2015 1:35:02 PM EST

2011 Hyundai Sonata Limited / SE

VIN: 5NPEC4AC8BH101189 Class: Mid Range Car - Lower

Year: 2011 Engine: 2.4L I4 DI

Make: Hyundai Country of Assembly: United States

Model: Sonata Limited / SE Vehicle Age: 4 year(s)

Style/Body: Sedan 4D Calculated Owners: 1





Accident Check Reported accidents: 1



Odometer Check Your vehicle checks out:





Title and Problem Check Your vehicle checks out:



Vehicle Use and Event Check Specific vehicle use(s) or events reported

This vehicle qualifies for Buyback Protection



Safeguard your investment with AutoCheck Buyback Protection. It reduces the risk in buying a used vehicle. About Buyback Protection

View Detailed History

 ∇

Accident Check

Not all accidents / issues are reported to AutoCheck.

Accident No.	Reported Date	Location
1	11/23/2012	HINGHAM, MA

人

Reported accidents or damage events are a result of vehicle collisions or other non-collision incidents such as vandalism or theft. Not all accidents or damage events are reported to AutoCheck.

Title and Problem Check



Your Vehicle Checks Out: AutoCheck's database for this 2011 Hyundai Sonata Limited / SE (5NPEC4AC8BH101189) shows no negative titles or other problems. When reported to AutoCheck, these events can indicate serious past damage or other significant problems, and disqualifies the vehicle for AutoCheck Buyback Protection. Check the Vehicle Use and Event Check for reported accidents that can affect vehicle safety and value.

0 Problem(s) 15 Title/Problem areas checked: Reported:

②	No abandoned title record
0	No damaged title or major damage incident record
	No fire damaged title record
©	No grey market title record
	No hail damage title record
0	No insurance loss title or probable total loss record
	No junk or scrapped title record
	No manufacturer buyback/lemon title record
②	No odometer problem title record
	No rebuilt/rebuildable title record
	No salvage title or salvage auction record
	No water damaged title record
	No NHTSA crash test record
②	No frame/unibody damage record
	No recycling facility record

Odometer Check



Your Vehicle Checks Out: AutoCheck examined the reported odometer readings reported to AutoCheck for this 2011 Hyundai Sonata Limited / SE (5NPEG4AG8BH101189) and no indication of an odometer rollback or tampering was found. AutoCheck uses business rules to determine if reported odometer readings are significantly less than previously reported values. Not all reported odometer readings are used. Title and auction events also report odometer tampering or breakage.









- □ X











Vehicle available as of 11/23/2015 12:11 PM Eastern Time

Leather Seats, Sunroof(s), Front Seat Heaters more...

No-haggle price **\$12,998***

CarMax Quality Certified

Estimate monthly payments

Quick Glance

Miles 81K 2WD Drive

Transmission Automatic

Exterior White Interior Burgundy EPA Mileage 22/35 MPG

12104904 Stock #

Rating (142)

142 reviews | Write a review

VIN 5NPEC4AC8BH101189

Free History Report

Open Recalls? VIN Look-Up FAQs

JAutoCheck

(916) 509-3965

\$1099 Transfer

to Sacramento South

▶ Get Financing Info

Ask a Question

Current Location North Attleboro 120 Draper Avenue North Attleboro, MA 02760 Deliberation Hours and directions

Overview

Features

History Report

Warranty & MaxCare ESP

Pricing & Financing

Safety, Reliability & Recalls

Reviews

Location

Trade-in

Safety Ratings

No data available for this vehicle.


▶ Safety ratings

D Dower quality ratings

Manufacturer Recalls

Contact a Sales Consultant

Email (916) 509-3965



Mobielo (via E

- Vehicle (via PDF)
- Non-Vehicle

Drive Safer

- Technology
- Driving Tips
- Tires
- Passenger Van Safety
- Emergency Response Vehicles
- Theft Prevention

SUMMARY:

HYUNDAI MOTOR AMERICA (HYUNDAI) IS RECALLING CERTAIN MODEL YEAR 2011-2012 SONATA VEHICLES MANUFACTURED DECEMBER 11, 2009, TO APRIL 12, 2012 AT HYUNDAI MOTOR MANUFACTURING ALABAMA AND EQUIPPED WITH EITHER A 2.0 LITER OR 2.4 LITER GASOLINE DIRECT INJECTION ENGINE. IN THE AFFECTED VEHICLES, METALLIC DEBRIS MAY NOT HAVE BEEN FULLY REMOVED DURING MANUFACTURING OF THE ENGINE CRANKSHAFT. IF THE DEBRIS WAS NOT COMPLETELY REMOVED, OIL FLOW MAY BE RESTRICTED THROUGH THE CONNECTING ROD BEARINGS, CAUSING CONNECTING ROD DAMAGE AND POSSIBLE ENGINE FAILURE. A WORN CONNECTING ROD BEARING WILL PRODUCE A METALLIC, CYCLIC KNOCKING NOISE FROM THE ENGINE AND POSSIBLE ENGINE FAILURE.

SAFETY RISK:

ENGINE FAILURE WOULD RESULT IN A VEHICLE STALL, INCREASING THE RISK OF A CRASH.

REMEDY:

REMEDY NOT YET AVAILABLE.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

OWNERS MAY ALSO CONTACT THE NAT'L HIGHWAY TRAFFIC SAFETY ADMIN VEHICLE SAFETY HOTLINE AT 1-888-327-4236(TTY 1-800-424-9153), OR GO TO WWW.SAFERCAR.GOV

THIS RECALL DATA LAST REFRESHED: Nov 21, 2015


Recall Date: November 16, 2015

NHTSA Recall Number: 15V759000

Manufacturer Recall Number: 136

SUMMARY:

HYUNDAI MOTOR AMERICA (HYUNDAI) IS RECALLING CERTAIN MODEL YEAR 2011-2012 SONATA VEHICLES MANUFACTURED DECEMBER 11, 2009 TO JUNE 30, 2011. IN THE AFFECTED VEHICLES. THE BRAKE PEDAL STOPPER PAD CAN



← → C 👚 https://vinrcl.safercar.gov/vin/vinLookup

Recall Date: July 18, 2014



2 - - X

THIS RECALL DATA LAST REFRESHED: Nov 21, 2015

NHTSA Recall Number: 14V434000 Manufacturer Recall Number: 123

SUMMARY:

HYUNDAI MOTOR COMPANY (HYUNDAI) IS RECALLING CERTAIN MODEL YEAR 2011-2014 SONATA VEHICLES MANUFACTURED DECEMBER 11, 2009, THROUGH MAY 29, 2014. IN THE AFFECTED VEHICLES, THE TRANSMISSION SHIFT CABLE MAY DETACH FROM FROM THE SHIFT LEVER PIN.

SAFETY RISK:

IF THE TRANSMISSION SHIFT CABLE DETACHES, THE TRANSMISSION GEAR SELECTION MAY NOT MATCH THE INDICATED GEAR AND THE VEHICLE MAY MOVE IN AN UNINTENDED OR UNEXPECTED DIRECTION, INCREASING THE RISK OF A CRASH, FURTHERMORE, WHEN THE DRIVER PARKS THE VEHICLE, DESPITE SELECTING THE 'PARK' POSITION, THE TRANSMISSION MAY NOT BE IN 'PARK.' IF THE VEHICLE IS NOT IN THE 'PARK' POSITION AND THE PARKING BRAKE IS NOT APPLIED, THERE IS A RISK THE VEHICLE WILL ROLL AWAY AS THE DRIVER AND OTHER OCCUPANTS EXIT THE VEHICLE OR ANYTIME THEREAFTER. A VEHICLE ROLLAWAY INCREASES THE RISK OF INJURY TO EXITING OCCUPANTS AND BYSTANDERS

REMEDY:

HYUNDAI WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT AND, AS NECESSARY, REPAIR THE CONNECTION BETWEEN THE SHIFT CABLE AND SHIFT LEVER, FREE OF CHARGE, THE MANUFACTURER HAS NOT YET PROVIDED A NOTIFICATION SCHEDULE. OWNERS MAY CONTACT HYUNDAI CUSTOMER SERVICE AT 1-855-671-3059. HYUNDAI'S NUMBER FOR THIS RECALL IS 123.

RECALL STATUS: Recall INCOMPLETE

MANUFACTURER NOTES:

OWNERS MAY ALSO CONTACT THE NAT'L HIGHWAY TRAFFIC SAFETY ADMIN VEHICLE SAFETY HOTLINE AT 1-888-327-4236(TTY 1-800-424-9153), OR GO TO WWW.SAFERCAR.GOV

THIS RECALL DATA LAST REFRESHED: Nov 21, 2015

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the Safety Issues section and follow the instructions there.

Recall information for this manufacturer is only available going back to October 19, 1996. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.