

You are here: Home / Vehicle Owners / VIN

- Search Safety Problems
 - › Vehicles
 - › Car Seats
 - › Tires
 - › Equipment
 - › Recalls by VIN
 - › Recalls FAQ
- Report Safety Problems
 - › Vehicle (Online)
 - › Vehicle (via PDF)
 - › Non-Vehicle
- Drive Safer
 - › Technology
 - › Driving Tips
 - › Tires
 - › Passenger Van Safety
 - › Emergency Response Vehicles
 - › Theft Prevention

Recalls Results by VIN - Vehicle Identification Number

[Print](#) [Share](#)

VIN: KM8J3CA48HU452860
Year: 2017 **Make:** Hyundai **Model:** TUCSON
Number of Open Recalls: 1

NHTSA Recall Number: [20V543000](#) **Recall Date:** September 4, 2020
Manufacturer Recall Number: 195

SUMMARY:
 HYUNDAI MOTOR AMERICA (HYUNDAI) IS RECALLING CERTAIN 2016-2021 TUCSON VEHICLES. THE ANTI-LOCK BRAKE HYDRAULIC ELECTRONIC CONTROL UNIT (HECU) COULD CORRODE INTERNALLY AND CAUSE AN ELECTRICAL SHORT, POSSIBLY RESULTING IN AN ENGINE COMPARTMENT FIRE.

SAFETY RISK:
 THE SUBJECT VEHICLES ARE EQUIPPED WITH ANTI-LOCK BRAKE SYSTEM ("ABS") MODULES THAT COULD MALFUNCTION INTERNALLY AND CAUSE AN ELECTRICAL SHORT OVER TIME, AN ELECTRICAL SHORT COULD RESULT IN SIGNIFICANT OVERCURRENT IN THE ABS MODULE, INCREASING THE RISK OF AN ENGINE COMPARTMENT FIRE.

REMEDY:
 CUSTOMERS CAN CONTINUE DRIVING THESE VEHICLES; HOWEVER HYUNDAI RECOMMENDS PARKING THESE VEHICLES OUTSIDE AND AWAY FROM STRUCTURES UNTIL THE RECALL REMEDY IS COMPLETED. HYUNDAI PLANS TO NOTIFY OWNERS TO BRING THEIR VEHICLES TO THE NEAREST HYUNDAI DEALERSHIP FOR REPLACEMENT OF THE ABS MODULE FUSE. FOR MODEL YEAR 2019-2021 AFFECTED VEHICLES, THE ELECTRONIC STABILITY CONTROL ("ESC") SOFTWARE WILL REQUIRE AN UPDATE FOR USE WITH THE NEW FUSE. THE REMEDY PROCEDURE WILL BE PERFORMED AT NO CHARGE. HYUNDAI WILL PROVIDE REIMBURSEMENT TO OWNERS FOR REPAIRS ACCORDING TO THE PLAN SUBMITTED TO NHTSA ON MAY 16, 2018.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
 OWNERS MAY ALSO CONTACT THE NAT'L HIGHWAY TRAFFIC SAFETY ADMIN VEHICLE SAFETY HOTLINE AT 1-888-327-4236(TTY 1-800-424-9153), OR GO TO [WWW.SAFERCAR.GOV](#)

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Mar 12, 2021


Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues & Recalls](#) section and follow the instructions there.

Recall information for this manufacturer is only available going back to October 19, 1996. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

Enter another VIN here:

I'm not a robot
 

Submit