



The way car buying should be.®

[Find a Car](#)

[Sell Us Your Car](#)

[Research](#)

[Financing](#)

[Why CarMax](#)

[Find a Store](#)

Search

MyCarMax

[Sign in](#) | [Register](#)

Your Nearest Store

Oxnard

[Change](#) | [Contact Us](#) | [Map](#)

[Sell Us Your Car!](#)  
[Schedule an appraisal](#)

[Website Feedback](#)

[Previous car](#) | [Next car](#) | [Back to search results](#)



11 people saved this car  
[Set up a test drive now](#)



Print

[Save this car](#)



[View Full Screen](#)

CLICK TO ZOOM

1 of 34



## 2003 Honda Accord LX 4D Sedan

Cruise Control, Air Conditioning, ABS Brakes [more...](#)

No-haggle price **\$10,998\***

5-Day Money-Back Guarantee+.... ✓

Clean Title Guarantee+..... ✓

[CarMax Quality Certified](#) ..... ✓

[Estimate monthly payments](#)

### Quick Glance

Miles 121K

Drive 2WD

Transmission Automatic

Exterior Silver

Interior Black

EPA Mileage 24/33 MPG

Stock # 11101411

Rating 4.6 ★★★★★

[41 reviews](#) | [Write a review](#)

VIN 1HGCM56323A012005

[Free History Report](#)



**(310) 896-3812**

(866) 880-0216

▶ [Hold This Car](#)

▶ [Schedule Test Drive](#)

▶ [Schedule Appraisal](#)

▶ [Schedule Appointment](#)

▶ [Free Transfer](#)

to Oxnard

▶ [Get Financing Info](#)

▶ [Ask a Question](#)

#### Current Location

Torrance

18020 Hawthorne Boulevard

Torrance, CA 90504

▶ [Hours and directions](#)

Vehicle available as of 10/28/2014 4:08 PM Eastern Time

[Overview](#)

[Features](#)

[History Report](#)

[Warranty & MaxCare ESP](#)

[Pricing & Financing](#)

[Safety & Reliability](#)

[Reviews & Awards](#)

[Location](#)

[Trade-in](#)

### Features

• Cruise Control

• Air Conditioning

• ABS Brakes

• Power Locks

• Power Mirrors

• AM/FM Stereo

### Pricing and Financing

We believe you shouldn't have to argue to get a fair price, which is why all of our prices are "no-haggle." You'll get a great car at a great price, without all the stress and worry of traditional used-car sales.

**CarMax No-haggle price**

**\$10,998\***

safercar.gov

HOME

VEHICLE SHOPPERS

VEHICLE OWNERS

VEHICLE MANUFACTURERS

PARENTS CENTRAL

You are here: Home / Vehicle Owners VIN

Do You Have a Safety Problem or Complaint?

[File a Complaint Now](#)[Search for all Recalls, Complaints & Investigations](#)[Recalls Look-up by VIN \(Vehicle Identification Number\)](#)[Recalls FAQ](#)[Receive Updates for Latest Recalls](#)[Sign-up for Email Alerts](#)[Subscribe to RSS Feeds](#)[Resources](#)[Databases \(Flat Files\)](#)[Passenger Van Safety](#)[Emergency Response Vehicles](#)

## Recalls Results Look-up by VIN

[Print](#)**VIN:** 1HGCM56323A012005**Year:** 2003 **Make:** Honda **Model:** Accord Sedan**Number of Open Recalls:** 2**NHTSA Recall Number:** [14V-351](#)**Recall Date:** August 29, 2014**Manufacturer Recall Number:** JJ5**SUMMARY:**

AMERICAN HONDA MOTOR CO., INC. (HONDA) IS CONDUCTING A LIMITED REGIONAL RECALL FOR CERTAIN MODEL YEAR 2001-2007 ACCORD (4-CYLINDER), 2001-2002 ACCORD (V6), 2001-2005 CIVIC, 2002-2006 CR-V, 2003-2011 ELEMENT, 2002-2004 ODYSSEY, 2002-2007 PILOT AND 2006 RIDGELINE VEHICLES ORIGINALLY SOLD, OR CURRENTLY REGISTERED IN ALABAMA, FLORIDA, GEORGIA, HAWAII, LOUISIANA, MISSISSIPPI, SOUTH CAROLINA, TEXAS, PUERTO RICO AND THE U.S. VIRGIN ISLANDS, AND EQUIPPED WITH TAKATA-BRAND AIR BAG INFLATORS. UPON DEPLOYMENT OF THE DRIVER SIDE FRONTAL AIR BAG, EXCESSIVE INTERNAL PRESSURE MAY CAUSE THE INFLATOR TO RUPTURE.

**SAFETY RISK:**

IN THE EVENT OF A CRASH NECESSITATING DEPLOYMENT OF THE DRIVER SIDE FRONTAL AIR BAG, THE INFLATOR COULD RUPTURE WITH METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANTS.

**REMEDY:**

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE VEHICLES AND REPLACE ANY DEFECTIVE AIR BAG INFLATORS, AS NECESSARY, FREE OF CHARGE. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009. HONDA'S NUMBER FOR THIS RECALL IS JJ5, JG7, JG8, JG9, JH0, JH1 AND JH2.

**REMEDY:**

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL INSPECT THE VEHICLES AND REPLACE ANY DEFECTIVE AIR BAG INFLATORS, AS NECESSARY, FREE OF CHARGE. OWNERS MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009. HONDA'S NUMBER FOR THIS RECALL IS JJ5, JG7, JG8, JG9, JH0, JH1 AND JH2.

**RECALL STATUS: Recall INCOMPLETE**

**MANUFACTURER NOTES:**

*THIS RECALL DATA LAST REFRESHED: Oct 31, 2014*

**NHTSA Recall Number:** [14V-349](#)

**Recall Date:** September 10, 2014

**Manufacturer Recall Number:** JJ6

**SUMMARY:**

AMERICAN HONDA MOTOR CO., INC (HONDA) IS RECALLING CERTAIN MODEL YEAR 2002-2003 CIVIC, CR-V AND ODYSSEY VEHICLES, AND MODEL YEAR 2003 ACCORD, ELEMENT, AND PILOT VEHICLES TO ADDRESS A SAFETY DEFECT IN THE PASSENGER SIDE FRONTAL AIR BAG WHICH MAY PRODUCE EXCESSIVE INTERNAL PRESSURE CAUSING THE INFLATOR TO RUPTURE UPON DEPLOYMENT OF THE AIR BAG.

**SAFETY RISK:**

IN THE EVENT OF A CRASH NECESSITATING DEPLOYMENT OF THE PASSENGER'S FRONTAL AIR BAG, THE INFLATOR COULD RUPTURE WITH METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE PASSENGER SEAT OCCUPANT OR OTHER OCCUPANTS.

**REMEDY:**

HONDA WILL NOTIFY OWNERS, AND DEALERS WILL REPLACE THE PASSENGER AIR BAG INFLATOR, FREE OF CHARGE. OWNER'S MAY CONTACT HONDA CUSTOMER SERVICE AT 1-800-999-1009. NOTE: THIS IS AN EXPANSION OF NHTSA RECALL NO. 13V-132. HONDA'S NUMBER FOR THIS RECALL IS JJ6, JJ7, JJ8, JJ9, JK0 AND JK1.

**RECALL STATUS: Recall INCOMPLETE. Remedy not yet available**

**MANUFACTURER NOTES:**

*THIS RECALL DATA LAST REFRESHED: Oct 31, 2014*